


DEKRA Automotive Solutions

Vehicle details

VIN	WVWZZZAUZ KP582842	Brand	VOLKSWAGEN	Maintenance date	29/10/2024
Licence Plate	HSN90S	Model	Golf7Variant-BV5-2017	Maintenance mileage	52 304 km
Registration date	24/06/2019	Year	2019	Exterior Color	Other
Odometer	71 046 km	Engine size	-	interior Color	
Fuel	Diesel	Body Type	Estate	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	7		

Inspection Details

Inspection date	15/09/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Automatic Gearbox	✓
Central locking	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Adaptive Cruise Control (ACC)	✓

Removable element

Refill emergency kit	✓
Load cover	✓

Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓

DEKRA Automotive Solutions

Tyres

Dunlop 205/55/16 V Summer 3.0 mm		Dunlop 205/55/16 V Summer 3.0 mm	
Dunlop 205/55/16 V Summer 6.0 mm		Dunlop 205/55/16 V Summer 6.0 mm	

Winter kit

Pirelli 195/65/15 T Winter 5.0 mm		Pirelli 195/65/15 T Winter 5.0 mm	
Pirelli 195/65/15 T Winter 9.0 mm		Pirelli 195/65/15 T Winter 9.0 mm	

Damages

1		Part	Aftermarket wheel	2		Part	Tyre
		Position	-			Position	Front right
3		Damages	Scratched	4		Damages	Pierced
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Lumpsum replacement
5		Part	Bumper	6		Part	Registration plates
		Position	Front			Position	Front
		Damages	Scratched			Damages	Dented
		Severity	-			Severity	-
		Repair mode	Lumsum Paintworks			Repair mode	Lumpsum replacement
7		Part	Sill	8		Part	Door sill
		Position	Right			Position	Front left
		Damages	Dented			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Lumpsum repair			Repair mode	For info
9		Part	Steering wheel	10		Part	Wing
		Position	-			Position	Back left
		Damages	Scratched			Damages	Dented
		Severity	-			Severity	-
		Repair mode	Smart Repair			Repair mode	For info
		Part	Bumper			Part	Headlight
		Position	Back			Position	Back right
		Damages	Scratched			Damages	Damaged
		Severity	-			Severity	-
		Repair mode	Lumsum Paintworks			Repair mode	Smart Repair

DEKRA Automotive Solutions

11



Part

Wing

Position

Back right

Damages

Dented

Severity

-

Repair mode

For info

●

●

12



Part

Door

Position

Back right

Damages

Dented

Severity

-

Repair mode

For info

●

●

13



Part

Wing

Position

Front right

Damages

Dented

Severity

-

Repair mode

Lumpsum repair

●

●

●

●

●

●

14



Part

Windscreen

Position

-

Damages

Stone impact

Severity

-

Repair mode

Smart Repair

●

●

15



Part

Windscreen

Position

-

Damages

Stone impact

Severity

-

Repair mode

Smart Repair

●