



Volkswagen Golf (UKL): 1WSQ916

Vinnumber:	WVWZZZAUZKP605397	Versionname:	Golf VII Variant Trendline 1.6TDi 115pk/cv 5p
First Registrationdate:	30/08/2019	Fiscalpower:	
Expertise Mileage:	175585	Power Kw:	85
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 5 VIT		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Maintenance	0 jours ou 3400 km		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	SD present		

Tyres

	195/65/15/91 H			
Winter tyres:	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				195/65 R 15 91 H
Tyre size FR				195/65 R 15 91 H
Tyre size RL				195/65 R 15 91 H
Tyre size RR				195/65 R 15 91 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Service, Maintenance, Check



Seat cover FR, Stain, Cleaning



Backrest cover FR, Stain, Acceptable



Seat cover R, Stain, Cleaning



Seat cover FL, Stain, Cleaning



Backrest cover FL, Worn, Check



Interior, Not original part, Check



Ignition key, Not functioning (well), Check



Bonnet, Stone chip(s), Acceptable



Bumper F, Scratch(es), Repair and paint (complete)



Wheel cover FL, Not original part, Replace



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Acceptable



Door FL, Dent(s) and scratch(es), Repair and paint (complete)




Door RL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Wheel cover RL, Not original part, Replace



Wing RL, Dent(s), Paintless dent repair



Internal boot lining L, Scratch(es), Smart repair



Internal boot lining R, Scratch(es), Smart repair



Interior covering C pillar R, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Boot carpet, Stain, Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Wheel aperture RR, Scratch(es), Acceptable



Wheel aperture RL, Scratch(es), Acceptable




Wheel cover RR, Not original part, Replace



Wheel cover FR, Not original part, Replace



Door FR, Dent(s) and scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Wing RR, Dent(s), Paintless dent repair



Roof, Chemical polution, Repair and paint (complete)

