



VOLKSWAGEN Golf VII

Golf Sportsvan 1.5 TSI ACT OPF DSG

VIN NO WVWZZZAUZKW674069
Registration Number UZKW674069



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-06-01	2	2	118142 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2019-06-27	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250909123344
Inspection Date / Place	2025-09-09 / BCA Neuss	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Gearbox Type	Automatic
Colour	Blue	Engine Size (cc)	1498
Engine Size	1.5	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	117

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	USB Socket	Alloys wheels	Bluetooth telephone interface
Front fog lamps	Headlamp wash/wipe	Remote adjusting wing mirrors	Reversing Camera
Satellite navigation	CD Player	Leather steering wheel	Radio
Tow ball	Airbag Status	Anti-lock braking	Cruise control
Front parking sensors	Heated wing mirrors	Remote central locking	Roof rails
Stability control	Electrically folding wing mirrors	LED Headlamps	Rear parking sensors

Equipment Details


Tow Ball Type	Pivoted	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	17	Extra Wheel / Tyre Set	Winter Tyres - Alloy
Seat Heating	Front		

Wheels & Tyres

Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6
Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	7	Extra Wheel - 4 Tyre Depth	7

Cosmetic Damage

29 Schäden



0 Schäden




Component		Damage	Comments
1	Rocker Panel / Center Left	Paint / Scratch / Scuff	
2	Pillar / Back Left	Paint / Scratch / Scuff	
3	Pillar / Back Right	Paint / Scratch / Scuff	
4	Rocker Panel / Center Right	Paint / Scratch / Scuff	
5	Hood	Bodywork / Dent / Dent	
6	Hood	Paint / Stone Chip	
7	Corner Bumper / Front Right	Paint / Scratch / Scuff	
8	Bumper / Front	Paint / Scratch / Scuff	
9	Corner Bumper / Front Left	Paint / Scratch / Scuff	
10	Fender / Front Left	Bodywork / Dent / Dent	
11	Door / Front Left	Bodywork / Dent / Dent	
12	Door / Back Left	Bodywork / Dent / Dent	

13	Door / Back Left	Bodywork / Dent / Dent
14	Fender / Back Left	Bodywork / Dent / Dent
15	Fender / Back Left	Bodywork / Dent / Dent
16	Rim / Back Left	Out of Bodywork / Scratch
17	Fender / Back Left	Paint / Scratch / Scuff
18	Roof	Bodywork / Dent / Dent
19	Bumper / Back	Paint / Scratch / Scuff
20	Tailgate	Bodywork / Dent / Dent
21	Corner Bumper / Back Right	Paint / Scratch / Scuff
22	Rim / Back Right	Out of Bodywork / Scratch
23	Fender / Back Right	Paint / Scratch / Scuff
24	Door / Back Right	Paint / Scratch / Scuff
25	Door / Back Right	Bodywork / Dent / Dent
26	Fender / Front Right	Bodywork / Dent / Dent
27	Fender / Front Right	Bodywork / Dent / Dent
28	Mirror Shell / Front Right	Paint / Scratch / Scuff
29	Door / Front Left	Paint / Scratch / Scuff



1. Rocker Panel / Center Left
Paint / Scratch / Scuff -




2. Pillar / Back Left
Paint / Scratch / Scuff -




3. Pillar / Back Right
Paint / Scratch / Scuff -



4. Rocker Panel / Center Right
Paint / Scratch / Scuff -



5. Hood
Bodywork / Dent / Dent -



6. Hood
Paint / Stone Chip -



7. Corner Bumper / Front Right
Paint / Scratch / Scuff -




8. Bumper / Front
Paint / Scratch / Scuff -




9. Corner Bumper / Front Left
Paint / Scratch / Scuff -




10. Fender / Front Left
Bodywork / Dent / Dent -




11. Door / Front Left
Bodywork / Dent / Dent -




12. Door / Back Left
Bodywork / Dent / Dent -



13. Door / Back Left
Bodywork / Dent / Dent -



14. Fender / Back Left
Bodywork / Dent / Dent -




15. Fender / Back Left
Bodywork / Dent / Dent -



16. Rim / Back Left
Out of Bodywork / Scratch -




17. Fender / Back Left
Paint / Scratch / Scuff -



18. Roof
Bodywork / Dent / Dent -



19. Bumper / Back
Paint / Scratch / Scuff -




20. Tailgate
Bodywork / Dent / Dent -




21. Corner Bumper / Back Right
Paint / Scratch / Scuff -




22. Rim / Back Right
Out of Bodywork / Scratch -




23. Fender / Back Right
Paint / Scratch / Scuff -




24. Door / Back Right
Paint / Scratch / Scuff -



25. Door / Back Right
Bodywork / Dent / Dent -




26. Fender / Front Right
Bodywork / Dent / Dent -



27. Fender / Front Right
Bodywork / Dent / Dent -



28. Mirror Shell / Front Right
Paint / Scratch / Scuff -



29. Door / Front Left
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)