



Volkswagen Golf: G419TS

Vinnnummer:	WVWZZZAUZL8903908	Versionname:	e-Golf VII 100kW/35,8kWh accu automaat
First Registrationdate:	16/12/2019	Fiscalpower:	
Expertise Mileage:	84740	Power Kw:	100
Bodytype:		Body colour:	Atlantic Blue metallic
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	641
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Central consol F
GPS		Luggage cover
Autom climate control		Headlights Xenon/LED/Laser
Windows electric F		Front parking sensors
Radio multimedia		Rear parking sensors

Degree of wear

205/55/16/91 Q				
Summer tyres:	Fr.L.	Bridgestone: 3,7 mm	Fr.R.	Bridgestone: 3,5 mm
	Re.L.	Bridgestone: 2,8 mm	Re.R.	Bridgestone: 4,3 mm
Tyre profile depth FL				3.7
Tyre profile depth FR				3.5
Tyre profile depth RL				2.8
Tyre profile depth RR				4.3
Tyre size FL				205/55 R 16 91 Q
Tyre size FR				205/55 R 16 91 Q
Tyre size RL				205/55 R 16 91 Q
Tyre size RR				205/55 R 16 91 Q
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace and paint



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Repair and paint (complete)



Outer door handle FR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)

