



VOLKSWAGEN GOLF VII: 1XAQ535

Vinnnumber:	WVWZZZAUZLP008461	Versionname:	1.6 TDi Trendline
First Registrationdate:	28/10/2019	Fiscalpower:	
Expertise Mileage:	56312	Power Kw:	85
Bodytype:		Body colour:	Blue
Gearbox:	MAN 5 VIT	Type of rims (mounted):	Steel
Transmission:		Parking lot:	2630
Fueltype:	Diesel		
Type of rims (mounted):	Steel		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Steering wheel multifunctional:		Front parking sensors:	
Radio multimedia:		Rear parking sensors:	
Type of headlighting:	Headlighting Halogen	Type of Tow bar:	No Tow bar
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Degree of wear

195/65/15/92 H				
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				195/65 R 15 92 H
Tyre size FR				195/65 R 15 92 H
Tyre size RL				195/65 R 15 92 H
Tyre size RR				195/65 R 15 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	453,05
Wheel cover FL, Scratch(es), Replace	54,66



Bumper R, Scratch(es), Repair and paint (complete)		289,07
		
Rear window, Scratch(es), Acceptable		0,00
		
Wheel cover FR, Scratch(es), Replace		54,66
		
Wing FR, Dent(s), Acceptable		0,00
		
Door RR, Scratch(es), Acceptable		0,00
		
Wing RR, Dent(s), Acceptable		0,00
		
Wheel cover RR, Scratch(es), Replace		54,66
		