



VOLKSWAGEN GOLF VII: 1XKD141			
Vinnnumber:	WVWZZZAUZLW096377	Versionname:	1.0 TSi Comfortline
First Registrationdate:	22/01/2020	Fiscalpower:	
Expertise Mileage:	73169	Power Kw:	85
Bodytype:		Body colour	Black
Gearbox:	MAN 6 VIT	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	1514
Fueltype:	Petrol		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		
Options			
Number of keys total	2	Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Tyres			
Summer tyres:	205/55/16/91 W		
	Fr.L.	Michelin: 4 mm	Fr.R. Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R. Michelin: 4 mm
Tyre profile depth FL			4.0
Tyre profile depth FR			4.0
Tyre profile depth RL			4.0
Tyre profile depth RR			4.0
Tyre size FL			205/55 R 16 91 W
Tyre size FR			205/55 R 16 91 V
Tyre size RL			205/55 R 16 91 W
Tyre size RR			205/55 R 16 91 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			261
Tyre make FR			261
Tyre make RL			261
Tyre make RR			261
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		
Total cost ex VAT			1473,73
Bonnet, Chemical polution, Repair and paint (complete)			395,90



Windscreen, Stone chip(s), Acceptable

0,00



Door FL, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Rear spoiler, Chemical polution, Polish

0,00



Wing FR, Dent(s), Acceptable

0,00



Wing RR, Chemical polution, Repair and paint (complete)

420,65



Roof, Chemical polution, Repair and paint (complete)

657,18

