


Vehicle details

VIN	WVWZZZAWZ KU065980	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	G8-63-FG	Model	POLO 1.0 TSI 70kW ActieAuto 5d Comfortline	Maintenance mileage	-
Registration date	10/09/2019	Year	2019	Exterior Color	Blue Metallic
Odometer	202 072 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	15/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element


Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 185/65/15 Summer 5.0 mm



Pirelli 185/65/15 Summer 5.0 mm



Pirelli 185/65/15 Summer 5.5 mm

Pirelli 185/65/15 Summer 5.0 mm

Exterior

1		Part Position Damages Severity Repair mode	Step plate Front left Dent & Chips - For info
5		Part Position Damages Severity Repair mode	Bumper Front Scratched Length (cm) > 10 Repair
7		Part Position Damages Severity Repair mode	Windscreen - Stone impact - Smart Repair
2		Part Position Damages Severity Repair mode	Bumper Back Scratched Length (cm) > 10 Repair
6		Part Position Damages Severity Repair mode	Bonnet - Chemical deposit - Lumpsum repair

Interior damage

3		Part Position Damages Severity Repair mode	Interior tailgate lining Up Scratched - Replace
4		Part Position Damages Severity Repair mode	Interior tailgate lining Down Scratched - Replace