


Vehicle details

VIN	WVWZZZAWZ KU094049	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	ZS-67-4N	Model	POLO 1.0 TSI 70kW Comfortline 5d	Maintenance mileage	-
Registration date	02/08/2019	Year	2019	Exterior Color	Blue Metallic
Odometer	183 172 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	11/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Rear parcel shelf	✓
Spare wheel kit	✗

Technical Document

User manual	✓
Warranty booklet	✓
Remote key	✓
Sat Nav CD ROM Software	✓
Spare key	✗

Tyres

Winter kit

Goodyear 165/65/15 Winter 6.0 mm		Goodyear 165/65/15 Winter 7.0 mm	
Bridgestone 165/65/15 Winter 2.0 mm		Bridgestone 165/65/15 Winter 3.5 mm	

Exterior

1



Part	Spare wheel kit
Position	-
Damages	Missing
Severity	-
Repair mode	For info

●

3



Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

●●●●

5



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

●●

8



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

●●

9



Part	Tailgate / Boot door
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

●●

10




Part	Step plate
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

●●

Interior damage

2



●

Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

6



● ●

Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

7



● ● ●

Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

Others

4		<table><tr><td>Part</td><td>Damage appraisal</td></tr><tr><td>Position</td><td>-</td></tr><tr><td>Damages</td><td>Stone impact</td></tr><tr><td>Severity</td><td>-</td></tr><tr><td>Repair mode</td><td>For info</td></tr></table>	Part	Damage appraisal	Position	-	Damages	Stone impact	Severity	-	Repair mode	For info	
Part	Damage appraisal												
Position	-												
Damages	Stone impact												
Severity	-												
Repair mode	For info												