


Vehicle details

VIN	WVWZZZAWZ KY065666	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	XH-87-7J	Model	POLO 1.0 TSI 70kW Comfortline 5d	Maintenance mileage	-
Registration date	15/01/2019	Year	2019	Exterior Color	Blue Metallic
Odometer	103 340 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	15/08/2025	Inspection loc.	Dekra Ayvens		
-----------------	------------	-----------------	--------------	--	--



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element


Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Dunlop 185/65/15 Summer 5.0 mm



Dunlop 185/65/15 Summer 4.5 mm



Dunlop 185/65/15 Summer 5.0 mm

Dunlop 185/65/15 Summer 4.0 mm

Exterior

1



●●

Part	Exterior door mirror shell
Position	Front left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

2



●●●

Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Repair

3



●●

Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

5




●●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

Interior damage

4



Part	Interior cleaning
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning