


### Vehicle details

VIN	WWWZZAWZ KY132503	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	XT-18-0K	Model	POLO 1.0 TSI 95pk Highline	Maintenance mileage	-
Registration date	20/03/2019	Year	2019	Exterior Color	Black Metallic
Odometer	97 493 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Manual	CO2	-
Doors	5	Gears	-		

### Inspection Details


Inspection date	03/04/2026	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------









Generic equipment	Removable element	Technical Document
Automated air-conditioning ✓	Spare wheel kit ✓	User manual ✓
Cruise control ✓	Rear parcel shelf ✓	Spare key ✓
Leather ✓		Remote key ✓
GPS system ✓		
Sliding roof ✓		
Alloy wheel rims ✓		
Central locking ✓		
Electric windows ✓		
Audio System ✓		

### Tyres

#### Winter kit



Exterior

<p>1</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper moulding</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Bumper moulding	Position	Front left	Damages	Scratched	Severity	-	Repair mode	Replace	<p>2</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) &gt; 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Front left	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair
Part	Bumper moulding																						
Position	Front left																						
Damages	Scratched																						
Severity	-																						
Repair mode	Replace																						
Part	Bumper																						
Position	Front left																						
Damages	Scratched																						
Severity	Length (cm) > 10																						
Repair mode	Repair																						
<p>3</p>  <p>● ● ●</p>	<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) &gt; 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Back	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair	<p>4</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Alloy wheel 17"</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 17"	Position	Front left	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair
Part	Bumper																						
Position	Back																						
Damages	Scratched																						
Severity	Length (cm) > 10																						
Repair mode	Repair																						
Part	Alloy wheel 17"																						
Position	Front left																						
Damages	Scratched																						
Severity	-																						
Repair mode	Lumpsum repair																						
<p>5</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Alloy wheel 17"</td></tr> <tr><td>Position</td><td>Front right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Lumpsum repair</td></tr> </table>	Part	Alloy wheel 17"	Position	Front right	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair	<p>6</p>  <p>● ●</p>	<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) &gt; 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Door	Position	Back left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Alloy wheel 17"																						
Position	Front right																						
Damages	Scratched																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Door																						
Position	Back left																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						