

Vehicle details

VIN	WVWZZZAWZ LU038724	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	G9-17-TF	Model	POLO 1.0 TSI 70kW ActieAuto 5d Comfortline	Maintenance mileage	-
Registration date	11/12/2019	Year	2019	Exterior Color	White Solid
Odometer	152 317 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	05/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres



Exterior

1		Part	Step plate	2		Part	Door
		Position	Front left			Position	Front left
		Damages	Scratched			Damages	Dented
		Severity	-			Severity	Diameter (mm) > 20
		Repair mode	For info			Repair mode	Smart Repair

3





Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

4





Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

5





Part	Wing
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6





Part	Wing
Position	Back right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

7





Part	Wing
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

8





Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair