


Vehicle details

VIN	WWWZZZAWZ LU039439	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	G1-12-XZ	Model	POLO 1.0 TSI 70kW 7-DSG Highline 5d	Maintenance mileage	-
Registration date	06/01/2020	Year	2020	Exterior Color	Orange Metallic
Odometer	92 720 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	07/04/2026	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------




Generic equipment	
Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓




Removable element	
Rear parcel shelf	✓

Technical Document	
User manual	✓
Spare key	✓
Remote key	✓

Tyres



Exterior

<p>1</p>  <p>● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Alloy wheel 16"</td> </tr> <tr> <td>Position</td> <td>Front left</td> </tr> <tr> <td>Damages</td> <td>Scratched</td> </tr> <tr> <td>Severity</td> <td>-</td> </tr> <tr> <td>Repair mode</td> <td>Lumpsum repair</td> </tr> </tbody> </table>	Part	Alloy wheel 16"	Position	Front left	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair	<p>2</p>	 <p>● ●</p> <table border="1"> <tbody> <tr> <td>Part</td> <td>Bumper</td> </tr> <tr> <td>Position</td> <td>Back</td> </tr> <tr> <td>Damages</td> <td>Scratched</td> </tr> <tr> <td>Severity</td> <td>-</td> </tr> <tr> <td>Repair mode</td> <td>Repair</td> </tr> </tbody> </table>	Part	Bumper	Position	Back	Damages	Scratched	Severity	-	Repair mode	Repair
Part	Alloy wheel 16"																						
Position	Front left																						
Damages	Scratched																						
Severity	-																						
Repair mode	Lumpsum repair																						
Part	Bumper																						
Position	Back																						
Damages	Scratched																						
Severity	-																						
Repair mode	Repair																						
<p>3</p>  <p>● ●</p>	<table border="1"> <tbody> <tr> <td>Part</td> <td>Alloy wheel 16"</td> </tr> <tr> <td>Position</td> <td>Front right</td> </tr> <tr> <td>Damages</td> <td>Scratched</td> </tr> <tr> <td>Severity</td> <td>-</td> </tr> <tr> <td>Repair mode</td> <td>Lumpsum repair</td> </tr> </tbody> </table>	Part	Alloy wheel 16"	Position	Front right	Damages	Scratched	Severity	-	Repair mode	Lumpsum repair												
Part	Alloy wheel 16"																						
Position	Front right																						
Damages	Scratched																						
Severity	-																						
Repair mode	Lumpsum repair																						