


Vehicle details

VIN	WWWZZAWZ LU072395	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	H6-16-VX	Model	POLO 1.0 TSI 70kW Comfortline Business 5d	Maintenance mileage	-
Registration date	10/06/2020	Year	2020	Exterior Color	Orange Metallic
Odometer	133 428 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	10/07/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 185/65/15 Summer 4.0 mm



Pirelli 185/65/15 Summer 4.0 mm



Pirelli 185/65/15 Summer 4.0 mm

Pirelli 185/65/15 Summer 4.0 mm

Exterior

<p>1</p>  <p>● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </tbody> </table>	Part	Wing	Position	Back left	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair	<p>2</p>  <p>● ● ● ● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Dent & Chips</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </tbody> </table>	Part	Bumper	Position	Back	Damages	Dent & Chips	Severity	-	Repair mode	Replace
Part	Wing																						
Position	Back left																						
Damages	Scratched																						
Severity	Length (cm) > 10																						
Repair mode	Repair																						
Part	Bumper																						
Position	Back																						
Damages	Dent & Chips																						
Severity	-																						
Repair mode	Replace																						
<p>3</p>  <p>● ● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </tbody> </table>	Part	Wing	Position	Back right	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	<p>4</p>  <p>● ● ● ● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Bonnet</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </tbody> </table>	Part	Bonnet	Position	Front	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Repair
Part	Wing																						
Position	Back right																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Smart Repair																						
Part	Bonnet																						
Position	Front																						
Damages	Dented																						
Severity	Diameter (mm) > 20																						
Repair mode	Repair																						
<p>5</p>  <p>● ● ● ● ● ● ● ●</p>	<table border="1"> <tbody> <tr><td>Part</td><td>Roof</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Hail damaged</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </tbody> </table>	Part	Roof	Position	-	Damages	Hail damaged	Severity	-	Repair mode	Smart Repair												
Part	Roof																						
Position	-																						
Damages	Hail damaged																						
Severity	-																						
Repair mode	Smart Repair																						