

VIN	WVWZZZAWZ LU075950	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	J3-07-BN	Model	POLO 1.0 TSI 70kW ACT1 5d Comfortline 5d	Maintenance mileage	-
Registration date	21/09/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	103 070 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection date	30/09/2025	Inspection loc.	Dekra Ayyens
-----------------	------------	-----------------	--------------



Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Spare wheel kit	
Rear parcel shelf	

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Continental 185/65/15 Summer 7.0 mm

Continental 185/65/15 Summer 5.5 mm

Goodyear 185/65/15 Summer 7.0 mm

Goodyear 185/65/15 Summer 3.5 mm

Exterior

1



● ●

Part	Wing
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

4



● ●

Part	Bumper
Position	Back right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

5



● ● ●

Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6




● ● ● ● ●

Part	Roof
Position	-
Damages	Hail damaged
Severity	Diameter (mm) > 20
Repair mode	Repair

Interior damage

2



Part	Interior cleaning
Position	Front right
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

●●●

3



Part	Interior tailgate lining
Position	Up
Damages	Scratched
Severity	-
Repair mode	Replace

●●