


Vehicle details

VIN	WVWZZZAWZ LU075974	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	J3-08-BN	Model	POLO 1.0 TSI 70kW ACTI 5d Comfortline 5d	Maintenance mileage	-
Registration date	29/09/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	85 015 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	30/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 185/65/15 Summer 2.5 mm	Continental 185/65/15 Summer 1.5 mm
Continental 185/65/15 Summer 4.5 mm	Continental 185/65/15 Summer 4.0 mm

Exterior

2		Part Position Damages Severity Repair mode	Door Back left Dented Diameter (mm) > 20 Smart Repair	3		Part Position Damages Severity Repair mode	Bumper Back Scratched Length (cm) > 10 Repair
4		Part Position Damages Severity Repair mode	Door Back right Dented Diameter (mm) > 20 Smart Repair	5		Part Position Damages Severity Repair mode	Bumper Front Scratched Length (cm) > 10 Repair
6		Part Position Damages Severity Repair mode	Bonnet - Chemical deposit - Lumpsum repair	7		Part Position Damages Severity Repair mode	Roof - Chemical deposit - Lumpsum repair
8		Part Position Damages Severity Repair mode	Roof wind deflector - Chemical deposit - Lumpsum repair				

Interior damage

1		Part Position Damages Severity Repair mode	Interior cleaning Front right Stained/dirty - Cleaning
---	---	--	--