


Vehicle details

VIN	WVWZZZAWZ LU077076	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	H1-36-XZ	Model	POLO 1.0 TSI 70kW ActieAuto 5d Comfortline	Maintenance mileage	-
Registration date	22/06/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	78 535 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	30/07/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

Spare key	✗
User manual	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 185/65/15 Summer 4.0 mm



Continental 185/65/15 Summer 4.0 mm



Continental 185/65/15 Summer 4.0 mm

Continental 185/65/15 Summer 4.0 mm

Exterior

2



Part

Bumper

Position

Back

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

●

●

3



Part

Door

Position

Back right

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

4



Part

Door

Position

Front right

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

●

●

5



Part

Wing

Position

Front right

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

6



Part

Bumper

Position

Front

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

●

●

●

7



Part

Bonnet

Position

Front

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

●

●

Interior damage

1



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

8



Part	Fabric seat
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning