

J064BN

J064BN · 1.0 TSI 95pk Comfortline · 26 September 2025 · Schiphol

Specifications

License Plate Number	J064BN	VIN	WVWZZZAWZLU077969
Manufacturer	VOLKSWAGEN	Cylinder Capacity	999 ^{cm³}
Model	Polo	Transmission Type	Handmatig geschakelde transmissie5
Model Versions	1.0 TSI 95pk Comfortline	MOT	17-07-2026
Body Type	5 door hatchback	First Admission	17-07-2020
Color	White	First Registration	17-07-2020
Paint Type	Matte	Odometer	132.708 ^{Km}
BPM	€ 3.302	Numer Of Keys	2
Production Year	2020	Interior	Black
KW	70	Number Headrests	5
Fuel Type	Gasoline		





Accessories

ABS

Airbags

Audio System

Bluetooth car kit

Central door locking

Centre armrest

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Leather steering wheel

Manual air conditioning

Navigation system

Rear parking sensors

Roller cover / parcel shelf

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance 06-05-2025

Last maintenance odometer 123.270

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 ^{mm}	Vredestein	185 ^{mm}	65 ^{mm}	15 ^{inch}	All Season
Rear Left	6 ^{mm}	Vredestein	185 ^{mm}	65 ^{mm}	15 ^{inch}	All Season
Front Right	6 ^{mm}	Vredestein	185 ^{mm}	65 ^{mm}	15 ^{inch}	All Season
Rear Right	6 ^{mm}	Vredestein	185 ^{mm}	65 ^{mm}	15 ^{inch}	All Season
Spare Tire Type	Fully Fledged					
Spare Tire Profile	8 ^{mm}					

Damages



Damage Part	Notes	Repair Type	Acceptable
Bumper – Rear	Trekoog verwijderen	Acceptable	Yes



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Worn	Accu	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No



Damage Part

Skirt - Right

Damage Type

Scratch(es)

Repair Type

Spotrepair

Acceptable

No



Damage Part

Frontdoor - Right

Damage Type

small dents / small scratches

Repair Type

Panelbeating
& Spray

Acceptable

No



Damage Part

Wheelcover - Left Front

Damage Type

Damaged

Repair Type

Replace

Acceptable

No



Damage Part

Damage Type

Repair Type

Acceptable

Wheelcover - Right Rear

Damaged

Replace

No