


Vehicle details

VIN	WVWZZZAWZ LU100747	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	K2-16-RB	Model	POLO 1.0 TSI 70kW Highline Business R 5d	Maintenance mileage	-
Registration date	02/02/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	172 898 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	05/06/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Rear parcel shelf	✓
-------------------	---

Technical Document

User manual	✓
Spare key	✓
Remote key	✓

Tyres



Exterior

2



Part

Position

Damages

Severity

Repair mode

Wing

Front left

Dented

Diameter (mm) > 20

Smart Repair

●

●

3



Part

Position

Damages

Severity

Repair mode

Tailgate / Boot door

-

Dented

Diameter (mm) > 20

Smart Repair

●

●

●

4



Part

Position

Damages

Severity

Repair mode

Door

Back right

Dent & Chips

Diameter (mm) > 20

Repair

●

●

●

5



Part

Position

Damages

Severity

Repair mode

Bumper

Front

Scratched

Length (cm) > 10

Repair

●

●

●

●

●

6



Part

Position

Damages

Severity

Repair mode

Roof

-

Hail damaged

Diameter (mm) > 20

Smart Repair

●

●

●

●

●

●

●

●

Interior damage

1



Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Smart Repair