


Vehicle details

VIN	WVWZZZAWZ LU101856	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	J7-94-JV	Model	POLO 1.0 TSI 70kW ActieAuto 5d Comfortline APL	Maintenance mileage	-
Registration date	24/08/2020	Year	2020	Exterior Color	Black Metallic
Odometer	95 915 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	15/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Audio System	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 185/65/15 Summer 6.0 mm



Continental 185/65/15 Summer 5.0 mm



Hankook 185/65/15 Summer 4.0 mm

Hankook 185/65/15 Summer 3.5 mm

Exterior

2



Part	Wing
Position	Front left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

3



Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

4



Part

Bumper

Position

Back

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

●

●

5



Part

Wing

Position

Back right

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

●

●

6



Part

Door

Position

Back right

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

7



Part

Step plate

Position

Front right

Damages

Dented

Severity

-

Repair mode

For info

●

●

8



Part

Bumper

Position

Front

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●

●

●

●

9



Part

Roof

Position

-

Damages

Dent & Chips

Severity

Diameter (mm) > 20

Repair mode

Repair

●

●


●

●

●


Interior damage

1



Part	Interior cleaning
Position	Centre
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

10



Part	Interior cleaning
Position	Front left
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning