



Volkswagen Polo (UKL): 1YKU746

Vinnumber:	WVWZZZAWZLU113179	Versionname:	Polo Comfortline 1.0TSi 95pk/cv 5p
First Registrationdate:	24/09/2020	Fiscalpower:	
Expertise Mileage:	76462	Power Kw:	70
Bodytype:		Type of rims (mounted)	Steel
Gearbox:	MAN 5 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Steel		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	SD present		

Tyres

	185/65/15/88 H			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				185/65 R 15 88 H
Tyre size FR				185/65 R 15 88 H
Tyre size RL				185/65 R 15 88 H
Tyre size RR				185/65 R 15 88 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Floor covering FL, Worn, Check



Bumper F, Scratch(es), Acceptable



Windscreen, Stone chip(s), Acceptable



Wing FL, Dent(s), Paintless dent repair



Wheel cover FL, Scratch(es), Replace



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Boot lid covering R, Scratch(es), Acceptable



Boot cover, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Wheel cover RR, Scratch(es), Replace



Door RR, Scratch(es), Acceptable



Sill trim R, Scratch(es), Acceptable



Wheel cover FR, Scratch(es), Acceptable



Bodywork, Not original part, Remove lettering

