

Inspection Protocol



VW POLO 1.0 TSI OPF

Vehicle information

License plate	FUG16L	Inspected by	T.H.
Year model	2020	Date of inspection	2025-03-12
Manuf. year/month	2020-08	City	Björkvik
First day in traffic	2020-09	Keys	1
Colour	Vit	Service book	Elektronisk servicebok
Mileage	67 100 km	Latest service	-
Fuel	Bensin	Mileage at the latest service	-
Transmission	DSG Sekventiell	Summer tires	15" alu-fälg 3/3/4/4
Engine effect	70 kW	Winter tires	plåtfälg dubbat 5/5/5/5

Damages

Location	Damage	Comments	Costs excluding VAT
Keys	Extra key missing		180 €
Bumper, Front	Wide scratch		240 €
Total excl. VAT			420 €

Comments

extra nyckel saknas.

Service occasions

5000-MIL, 6500-MIL

Images

[See all images in large format](#)
















Stötfångare Fram Skrap 3 300 kr