


Vehicle details

VIN	VWZZZAWZ MU022476	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	K2-70-KX	Model	POLO 1.0 TSI 70kW Comfortline Business 5d	Maintenance mileage	-
Registration date	26/02/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	218 518 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	12/08/2025	Inspection loc.	Dekra Ayvens		
-----------------	------------	-----------------	--------------	--	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Pirelli 185/65/15 H Summer 4.0 mm		Pirelli 185/65/15 H Summer 4.0 mm	
Continental 185/65/15 H Summer 6.0 mm		Continental 185/65/15 H Summer 6.0 mm	

Exterior

1		Part Position Damages Severity Repair mode	Roof - Dent & Chips Diameter (mm) > 20 Repair	2		Part Position Damages Severity Repair mode	Bonnet - Scratched Length (cm) > 10 Repair
3		Part Position Damages Severity Repair mode	Bumper Front Scratched Length (cm) > 10 Repair	4		Part Position Damages Severity Repair mode	Headlight Front right Scratched - For info
5		Part Position Damages Severity Repair mode	Door Back left Dent & Chips Diameter (mm) > 20 Repair	6		Part Position Damages Severity Repair mode	Wing Back left Scratched Length (cm) > 10 Repair
7		Part Position Damages Severity Repair mode	Bumper Back Scratched Length (cm) > 10 Repair	8		Part Position Damages Severity Repair mode	Tailgate / Boot door - Dented Diameter (mm) > 20 Smart Repair
9		Part Position Damages Severity Repair mode	Wing Back right Dent & Chips Diameter (mm) > 20 Repair	10		Part Position Damages Severity Repair mode	Door Back right Dented Diameter (mm) > 20 Repair
11		Part Position Damages Severity Repair mode	Door Front right Dented Diameter (mm) > 20 Repair				

Interior damage

12		Part Position Damages Severity Repair mode	Interior cleaning - Stained/dirty - Cleaning
----	---	--	--