



VOLKSWAGEN Polo VI

Polo 1.0 TSI DSG OPF

VIN NO WVWZZZAWZMU042935
Registration Number WZMU042935



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-11-01	1	2	41152 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2021-09-15	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251009090025
Inspection Date / Place	2025-10-09 / BCA Neuss	Cosmetic Grade	5

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Gearbox Type	Automatic
Colour	Black	Engine Size (cc)	999
Engine Size	1.0	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	108

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

USB Socket	Alloys wheels	Bluetooth telephone interface	Front fog lamps
Heated wing mirrors	Remote central locking	Stability control	Leather steering wheel
Radio	Airbag Status	Anti-lock braking	Cruise control
Front parking sensors	Remote adjusting wing mirrors	Satellite navigation	Electrically folding wing mirrors
LED Headlamps	Rear parking sensors		

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	15
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front

Wheels & Tyres

Extra Wheel - 1 Tyre Depth	6	Extra Wheel - 2 Tyre Depth	6
Extra Wheel - 3 Tyre Depth	6	Extra Wheel - 4 Tyre Depth	6
Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

17 Schäden



0 Schäden



Component		Damage	Comments
1	Corner Bumper / Back Left	Paint / Scratch / Scuff	
2	Hood	Paint / Stone Chip	
3	Windshield / Front	Paint / Chipping	
4	Fender / Back Left	Bodywork / Dent / Dent	
5	Corner Bumper / Front Right	Paint / Scratch / Scuff	
6	Fender / Back Right	Paint / Scratch / Scuff	
7	Door / Front Left	Bodywork / Dent / Dent	
8	Pillar / Back Right	Paint / Scratch / Scuff	
9	Corner Bumper / Back Right	Paint / Scratch / Scuff	
10	Door / Front Right	Paint / Scratch / Scuff	
11	Fender / Back Left	Bodywork / Dent / Dent	
12	Tailgate	Bodywork / Dent / Dent	

13	Door / Front Right	Bodywork / Dent / Dent
14	Door / Back Right	Bodywork / Dent / Dent
15	Door / Front Left	Paint / Scratch / Scuff
16	Tailgate	Bodywork / Dent / Dent
17	Rim / Front Left	Out of Bodywork / Scratch




1. Corner Bumper / Back Left
Paint / Scratch / Scuff -



2. Hood
Paint / Stone Chip -



3. Windshield / Front
Paint / Chipping -




4. Fender / Back Left
Bodywork / Dent / Dent -



5. Corner Bumper / Front Right
Paint / Scratch / Scuff -



6. Fender / Back Right
Paint / Scratch / Scuff -




7. Door / Front Left
Bodywork / Dent / Dent -




8. Pillar / Back Right
Paint / Scratch / Scuff -




9. Corner Bumper / Back Right
Paint / Scratch / Scuff -




10. Door / Front Right
Paint / Scratch / Scuff -




11. Fender / Back Left
Bodywork / Dent / Dent -




12. Tailgate
Bodywork / Dent / Dent -




13. Door / Front Right
Bodywork / Dent / Dent -



14. Door / Back Right
Bodywork / Dent / Dent -



15. Door / Front Left
Paint / Scratch / Scuff -



16. Tailgate
Bodywork / Dent / Dent -



17. Rim / Front Left
Out of Bodywork / Scratch -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

AC / Heating System	✓	Main & Spare Keys Functioning	!
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓

Levels

Brakes Fluid	✓	Coolant Fluid	!
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)