



Volkswagen Polo: L151GL

Vinnumber:	WVWZZZAWZMU063458	Versionname:	Polo 1.0 TSI 70kW Comfortline Business
First Registrationdate:	12/05/2021	Fiscalpower:	
Expertise Mileage:	96127	Power Kw:	70
Bodytype:		Body colour:	Unilak Urano Grey
Gearbox:	MAN 5 VIT	Paint type:	Opaque
Transmission:	Front	Type of rims (mounted):	Steel
Fueltype:	Petrol	Parking lot:	377
Number of seats:	5		
Type of rims (mounted):	Steel		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Front parking sensors
Radio multimedia		Rear parking sensors

Degree of wear

185/65/15/88 H				
Summer tyres:	Fr.L.	Bridgestone: 5,6 mm	Fr.R.	Bridgestone: 4,8 mm
	Re.L.	Bridgestone: 7,2 mm	Re.R.	Bridgestone: 7,1 mm
Tyre profile depth FL				5.6
Tyre profile depth FR				4.8
Tyre profile depth RL				7.2
Tyre profile depth RR				7.1
Tyre size FL				185/65 R 15 88 H
Tyre size FR				185/65 R 15 88 H
Tyre size RL				185/65 R 15 88 H
Tyre size RR				185/65 R 15 88 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Interior, Stain, Cleaning



Door FL, Scratch(es), Repair and paint (complete)




Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Bonnet, Stone chip(s), Repair and paint (complete)




Bumper F, Scratch(es), Repair and paint (partial)



Wing FR, Stone chip(s), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)





Roof, Dent(s), Repair and paint (complete)

