

WVWZZZAWZNU068271

VOLKSWAGEN Polo VI Polo 1.0 TSI OPF DSG



TECHNICAL CONDITION

Engine	Brakes	Steering
Engine starts	Brake operation	Sounds normal
Engine operation	Clutch Clutch operation Idle sounds normal Clutch biting point	Gear Box Automatic shift Manual shif Warning light OK
Engine compartment dry (oil)		
Fume quantity		
Sounds normal		

COMPLAINT NOTE

The technical check includes a visual check of the vehicles without removal of any components.
The condition of the mechanical components cannot be rated.

LEVELS

Coolant fluid	
Brakes fluid	

EQUIPMENT TEST

Electric windows test	
Audio equipment	
Navigation equipment	
AC / Heating system	
Central lock system test	

TYRES

Profile depths

FL	FR
BR	BL

Additional tyre profil depths

A	B
C	D

CONTROL LIGHTS

Dashboard	
ABS	
Oil	
Airbag	
Engine	
Brakes	
Steering	
DPF	
Diesel heaters	
Traction control / ESP / Stability control	
4x4	
Alternator / Battery	



No defects recognizable, good condition or positive tests based on vehicle's age and mileage.



Registered damage that needs to be repaired by the buyer.



Not verifiable.