

P274GR

P274GR · 1.0 TSI 95pk DSG-7 R-Line Business+ · 26 September 2025 · Schiphol

Specifications

License Plate Number	P274GR	VIN	WVWZZZAWZNY029390
Manufacturer	VOLKSWAGEN	Cylinder Capacity	999 ^{cm3}
Model	Polo	Transmission Type	Handmatig geschakelde transmissie7
Model Versions	1.0 TSI 95pk DSG-7 R-Line Business+	MOT	15-03-2026
Body Type	5 door hatchback	First Admission	15-03-2022
Color	Blue	First Registration	15-03-2022
Paint Type	Metallic	Odometer	224.574 ^{Km}
BPM	€ 4.339	Numer Of Keys	2
Production Year	2022	Interior	Grey
KW	70	Number Headrests	5
Fuel Type	Gasoline		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric sliding roof

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior

Adequate

Maintenance Remarks

Olie verversen
Inspectie uitvoeren

Condition interior

Adequate

Previous Repairs

Unknown

Last Maintenance Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 ^{mm}	Vredestein	215 ^{mm}	45 ^{mm}	17 ^{inch}	All Season
Rear Left	6 ^{mm}	Vredestein	215 ^{mm}	45 ^{mm}	17 ^{inch}	All Season
Front Right	5 ^{mm}	Vredestein	215 ^{mm}	45 ^{mm}	17 ^{inch}	All Season
Rear Right	6 ^{mm}	Vredestein	215 ^{mm}	45 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Fully Fledged					
Spare Tire Profile	8 ^{mm}					

Damages



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Bedieningsknop	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Small dent(s)	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Windscreen – Front	Chipped	Window Repair	No



Damage Part

Damage Type

Repair Type

Acceptable

Alloy - Right Front

Damaged

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Front Right

Damaged

Acceptable

Yes



Damage Part

Damage Type

Notes

Repair Type Acceptable

Frontdoor - Right

Small scratch(es)

Deurklink

Acceptable Yes



Damage Part

Reardoor – Right

Damage Type

small dents / small scratches

Repair Type

Panelbeating & Spray

Acceptable

No



Damage Part

Fender – Rear Right

Damage Type


Small dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part

Interior

Damage Type

Worn

Repair Type

Cloth Repair

Acceptable

No



Damage Part	Damage Type	Repair Type	Acceptable
Co drivers seat	Stains & dirt	Cleaning	No