

Vehicle details

VIN	WVWZZZCD8 PW516002	Brand	VW	Maintenance date	-
Licence Plate	W83238K	Model	Golf 2.0 Tdi 85kw Variant 85KW	Maintenance mileage	-
Registration date	17/11/2022	Year	1000	Exterior Color	Silver Metallic
Odometer	184 791 km	Engine size	1968	interior Color	Black
Fuel	Diesel	Body Type	Estate	Next technical inspection	01/11/2025
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	05/03/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Xenon projectors	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Heating seats	✓

Removable element

--	--


Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Fulda 205/55/16 H Winter 4.3 mm



Fulda 205/55/16 H Winter 5.3 mm



Fulda 205/55/16 H Winter 5.6 mm

Fulda 205/55/16 H Winter 4.5 mm

Exterior

2		Part	Exterior cleaning	4		Part	Bumper
		Position	-			Position	Front
		Damages	Stained/dirty			Damages	Scratched
		Severity	-			Severity	Length (cm) > 10
		Repair mode	Cleaning			Repair mode	Repair

5



Part	Door
Position	Back left
Damages	Scratched
Severity	-
Repair mode	For info

6



Part	Wing
Position	Back left
Damages	Dented
Severity	-
Repair mode	Repair

7



Part	Door sill
Position	Back left
Damages	Dented
Severity	-
Repair mode	For info

8



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

9



Part	Rear light (wing)
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Replace

10



Part	Wing
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	Repair

Interior damage

1



●●●●

Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Replace

3



●●●●

Part	Steering wheel
Position	-
Damages	Stained/dirty
Severity	-
Repair mode	Replace

11



●●

Part	Fabric door lining
Position	Back right
Damages	Deformed
Severity	-
Repair mode	Replace

12



●●

Part	Fabric door lining
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Replace

Others

13



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint

14



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks