

VOLKSWAGEN GOLF VIII

WWWZZZCDZMW013906

Golf 2.0 SCR TDi Life 85 kw.



Km	139579	First use	15/09/2020	Summer	
Gearbox	Manual	Drive system		FrontLeft	Michelin 205/0/16/55 4 mm Mounted
Doors	5	Seats	5	RearLeft	Michelin 205/0/16/55 4 mm Mounted
Emission	Euro 6d	CO ₂	WLTP 107 gr/km	FrontRight	Michelin 205/0/16/55 4 mm Mounted
Fuel type	Diesel	HP/kW	115 / 85	RearRight	Michelin 205/0/16/55 4 mm Mounted
Colour ext.	-	Colour int.	-		

1G9: Space- and weight-saving spare wheel
6Q2: Gearshift knob in leather
8RT: 6+1 speakers
GPS: Storage:
QV3: Digital radio reception DAB+

1S1: Tool kit and jack
7UG: Navigation system 'Discover Pro' incl. Streaming & Internet
8T8: Adaptive Cruise Control ACC stop & go incl. speed limiter
QH1: Voice control

2FD: Leather-wrapped multi-function steering wheel
8AR: Radio
9WJ: App-Connect incl. App-Connect Wireless for Apple CarPlay
QK1: Multifunction camera

611: Lane keeping system Lane Assist
8J3: Auto. Emergency Braking Front Assist with Pedestrian and Cyclist Monitoring
ELS: Online service, with OCU, with head unit coding, without engine immobilizer interconnection
QR9: Dynamic Road Sign Display

EN - toit Chemical pollution	
EN - aile arrière gauche	
EN - porte avant gauche	
Ignition key Broken	
EN - pare-choc avant centre	
Sill outer L Scratch	
Luggage space cover Broken	
Dashboard Scratch	

Step L	✘ ✘ ✘ ✘
Step R	✘ ✘ ✘ ✘ ✘ ✘ ✘ ✘ ✘ ✘
Step L	✘ ✘ ✘ ✘ ✘ ✘
Rear spoiler Chemical polution	✘ ✘
Alloy rim R L Scratch	✘ ✘ ✘ ✘ ✘ ✘
Alloy rim F L Scratch	✘ ✘ ✘ ✘ ✘ ✘
Alloy rim R R Scratch	✘ ✘ ✘ ✘ ✘ ✘
Alloy rim F R Scratch	✘ ✘ ✘ ✘ ✘ ✘ ✘ ✘ ✘ ✘
Door mirror cover L Scratch	✘ ✘
Interior Dirty	✘ ✘ ✘ ✘ ✘ ✘ ✘ ✘ ✘ ✘
Floor covering R Broken	✘ ✘
Interior Damaged	✘ ✘ ✘ ✘ ✘ ✘ ✘ ✘ ✘ ✘

Bodywork Damaged	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
EN - porte arrière droite Repaired	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Tyre R R Used	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
EN - aile arrière droit Repaired	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>
Tyre F R Tear	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>