



Volkswagen Golf (UKL): 2AWY919

Vinnumber:	WVWZZZCDZMW128633	Versionname:	Golf VIII Life 1.5TSi 130pk/cv 5p
First Registrationdate:	23/08/2021	Fiscalpower:	
Expertise Mileage:	109607	Power Kw:	96
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	plus 7900 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/45/17/94 Y				
Summer tyres:	Fr.L.	Vredestein: 2 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm
Tyre profile depth FL	2.0			
Tyre profile depth FR	3.0			
Tyre profile depth RL	5.0			
Tyre profile depth RR	5.0			
Tyre size FL	225/45 R 17 94 Y			
Tyre size FR	225/45 R 17 94 Y			
Tyre size RL	225/45 R 17 94 Y			
Tyre size RR	225/45 R 17 94 Y			
Tyre type FL	All seasons			
Tyre type FR	All Seasons			
Tyre type RL	All seasons			
Tyre type RR	All Seasons			
Tyre make FL	2480			
Tyre make FR	2480			
Tyre make RL	2480			
Tyre make RR	2480			

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

MOT certificate, Non-conforme, Replace



Ignition key, Missing, Replace



Instrument panel, complete, Not functioning (well), Check




Interior, Dirty, Cleaning




Bumper F, Scratch(es), Repair and paint (complete)



Alloy rim FL polished, Scratch(es), Repair and paint (complete)




Door FL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Boot lid covering R, Broken, Replace



Bumper R, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RR polished, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Tyre FR, Tear, Replace

