



Volkswagen Golf (UKL): 2APK415

Vinnnumber:	WVWZZZCDZMW305444	Versionname:	Golf VIII R-Line 1.5e-TSi 150pk/cv 5p DSG7
First Registrationdate:	2/06/2021	Fiscalpower:	
Expertise Mileage:	184600	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Maintenance	min 100 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	225/40/18/92 Y			
Summer tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 2 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				3.0
Tyre profile depth RR				2.0
Tyre size FL				225/40 R 18 92 Y
Tyre size FR				225/40 R 18 92 Y
Tyre size RL				225/40 R 18 92 Y
Tyre size RR				225/40 R 18 92 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2484
Tyre make FR				2484
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Service, Maintenance, Check




Bumper F, Broken, Replace and paint



Bumper moulding F, Scratch(es), Acceptable



Bonnet, Dent(s), Paintless dent repair



Windscreen, Stone chip(s), Windscreen repair




Alloy rim RL polished, Scratch(es), Repair and paint (complete)




Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Repaired, Check



Door FR, Repaired, Check



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

