



Volkswagen Golf (UKL): 2BHF703

Vinnumber:	WVWZZZCDZNW125968	Versionname:	Golf VIII Life 2.0TDi 115pk/cv 5p
First Registrationdate:	25/11/2021	Fiscalpower:	
Expertise Mileage:	183672	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	4700.0		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/45/17/91 Y				
Summer tyres:	Fr.L.	Uniroyal: 6,2 mm	Fr.R.	Uniroyal: 6,1 mm
	Re.L.	Uniroyal: 8,1 mm	Re.R.	Uniroyal: 8 mm
Tyre profile depth FL				6.2
Tyre profile depth FR				6.1
Tyre profile depth RL				8.1
Tyre profile depth RR				8.0
Tyre size FL				225/45 R 17 91 Y
Tyre size FR				225/45 R 17 91 Y
Tyre size RL				225/45 R 17 91 Y
Tyre size RR				225/45 R 17 91 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				265
Tyre make FR				265
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Ignition key, Not functioning (well), Check



Door panel FL, Worn, Acceptable



Windscreen moulding, Scratch(es), Replace



Bonnet, Stone chip(s), Acceptable



Alloy rim RL polished, Scratch(es), Repair and paint (complete)



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Wing RL, Dent(s), Paintless dent repair



Boot lid covering R, Worn, Acceptable



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Roof, Rust, Repair and paint (complete)



Bodywork, Chemical polution, Check

