



Volkswagen Golf (UKL): 2CAC203

Vinnumber:	WVWZZZCDZNW525857	Versionname:	Golf VIII Variant Life 1.0TSi 110pk/cv 5p
First Registrationdate:	6/05/2022	Fiscalpower:	
Expertise Mileage:	137520	Power Kw:	81
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	+249 d		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/55/18/91 V				
Summer tyres:	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Nexen: 7 mm	Re.R.	Nexen: 7 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				205/55 R 18 91 V
Tyre size FR				205/55 R 18 91 V
Tyre size RL				205/55 R 18 91 V
Tyre size RR				205/55 R 18 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				1957072
Tyre make RR				1957072

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Door panel RL, Scratch(es), Smart repair



Door panel RR, Scratch(es), Acceptable



Armrest, Stain, Cleaning



Windscreen, Stone chip(s), Windscreen repair



Bumper F, Scratch(es), Acceptable



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Roof pillar L, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Bumper trim R, Scratch(es), Replace



Alloy rim FR, Scratch(es), Acceptable



Bodywork, Not original part, Remove lettering

