


DEKRA Automotive Solutions

Vehicle details

VIN	WVWZZZCDZ NW537160	Brand	VOLKSWAGEN	Maintenance date	22/08/2025
Licence Plate	EFC44H	Model	Golf-VIII-Variant-CG5-2020	Maintenance mileage	86 601 km
Registration date	07/10/2022	Year	2022	Exterior Color	Other
Odometer	90 658 km	Engine size	-	interior Color	
Fuel	Petrol	Body Type	Estate	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	7		

Inspection Details

Inspection date	10/10/2025	Inspection loc.	Eurotransport Kungsängen
-----------------	------------	-----------------	--------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
Bluetooth	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Central locking	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Lane Keeping Assist (LKA)	✓
Adaptive Cruise Control (ACC)	✓
Led lighting	✓

Removable element

Refill emergency kit	✓
Load cover	✓
Towing hook	✓

Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓

DEKRA Automotive Solutions

Tyres

Nexen 205/55/16 V Summer 5.0 mm		Nexen 205/55/16 V Summer 5.0 mm	
Nexen 205/55/16 V Summer 6.0 mm		Nexen 205/55/16 V Summer 6.0 mm	

Winter kit

Michelin 205/55/16 H Winter 6.0 mm		Michelin 205/55/16 H Winter 6.0 mm	
Pirelli 205/55/16 H Winter 9.0 mm		Pirelli 205/55/16 H Winter 9.0 mm	

Damages

1		Part: Aftermarket wheel Position: - Damages: Scratched Severity: - Repair mode: Lumpsum replacement	2		Part: Engine cover Position: - Damages: Broken Severity: - Repair mode: Lumpsum replacement
3		Part: Bumper Position: Front Damages: Scratched Severity: - Repair mode: Lumpsum Paintworks	4		Part: Alloy wheel Position: Front left Damages: Scratched Severity: - Repair mode: For info
5		Part: Door Position: Front left Damages: Dented Severity: - Repair mode: Smart Repair	6		Part: Wing Position: Back left Damages: Scratched Severity: - Repair mode: For info
7		Part: Bumper Position: Back Damages: Scratched Severity: - Repair mode: For info	8		Part: Wing Position: Back right Damages: Dented Severity: - Repair mode: Lumpsum repair
9		Part: Bonnet Position: - Damages: Stone impact Severity: - Repair mode: Lumpsum Paintworks	10		Part: Windscreen Position: - Damages: Broken Severity: - Repair mode: Lumpsum replacement