



**Volkswagen ID.3: K696BH**

Vinnnumber:	<b>WVWZZZE1ZLP012908</b>	Versionname:	<b>ID.3 150kW / 58kWH 1ST</b>
First Registrationdate:	<b>24/11/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>68048</b>	Power Kw:	<b>150</b>
Bodytype:		Body colour:	<b>Mangan Grey metallic</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>226</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Telephone equipment
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Headlights Xenon/LED/Laser
Radio multimedia		Front parking sensors
		Rear parking sensors

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 55 / 18 / 95 / T / Aluminium	6,2 mm	Michelin	Summer
	Right	215 / 55 / 18 / 95 / T / Aluminium	6,5 mm	Michelin	Summer
Rear	Left	215 / 55 / 18 / 95 / T / Aluminium	4,3 mm	Bridgestone	Summer
	Right	215 / 55 / 18 / 95 / T / Aluminium	4,1 mm	Bridgestone	Summer


**Assistance equipment**

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>1</b>

**Interior, Stain, Cleaning**



**Door RL, Bad repair, Repair and paint (complete)**



**Door FL, Scratch(es), Repair and paint (complete)**



Bonnet, Chemical polution, Polish




Bumper F, Scratch(es), Polish



Door FR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Repair and paint (complete)



Charging cable (normal), Missing, Replace



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)

