



Volkswagen ID.3: J944XL

Vinnumber:	WVWZZZE1ZMP006803	Versionname:	ID.3 150kW / 58kWh 1ST Plus automaat
First Registrationdate:	17/11/2020	Fiscalpower:	
Expertise Mileage:	93735	Power Kw:	150
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Paint type	Opaque
Transmission:	Front	Type of rims (mounted)	Aluminium
Fueltype:	Electric	Parking lot	471
Number of seats	5		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Telephone equipment
GPS		Lining Alcantara
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 50 / 19 / 93 / T / Aluminium	7,8 mm	Bridgestone	Winter
	Right	215 / 50 / 19 / 93 / T / Aluminium	7,6 mm	Bridgestone	Winter
Rear	Left	215 / 50 / 19 / 93 / T / Aluminium	5,8 mm	Bridgestone	Winter
	Right	215 / 50 / 19 / 93 / T / Aluminium	6,0 mm	Bridgestone	Winter

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Service, Maintenance, Execute



Interior, Stain, Cleaning



Door RL, Scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Polish



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Chemical polution, Polish



Door RR, Scratch(es), Repair and paint (complete)



Wing FR, Stone chip(s), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Polish



Roof pillar R, Scratch(es), Repair and paint (complete)



Charging cable (normal), Missing, Replace



Bumper R, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Rear spoiler, Scratch(es), Repair and paint (complete)

