


**Vehicle details**

VIN	WVWZZZE1Z MP010185	Brand	VOLKSWAGEN	Maintenance date	-
Licence Plate	K9-62-GZ	Model	ID.3 58kWh 1st Plus 5d ActieAuto	Maintenance mileage	-
Registration date	16/12/2020	Year	2020	Exterior Color	White Solid
Odometer	125 560 km	Engine size	-	interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

**Inspection Details**

Inspection date	14/11/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



**Generic equipment**

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


**Removable element**

Rear parcel shelf	✓
Vehicle charger	✓

**Technical Document**

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

## Tyres



Michelin 215/50/19 Summer 5.0 mm  Michelin 215/50/19 Summer 5.0 mm 

Michelin 215/50/19 Summer 4.5 mm  Michelin 215/50/19 Summer 4.5 mm 

## Exterior

5



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

● ● ● ● ●

## Interior damage

1



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

● ● ● ● ●

2



Part	Interior tailgate lining
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Replace

● ● ●

3



Part	Interior tailgate lining
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Replace

● ● ●

## Others

4



Part	Wireless charger
Position	-
Damages	Missing
Severity	-
Repair mode	For info

●

Page 2/2