



Volkswagen ID.3: N833KR

Vinnumber:	WVWZZZE1ZMP081870	Versionname:	ID.3 110kW / 45kWh automaat
First Registrationdate:	11/11/2021	Fiscalpower:	
Expertise Mileage:	68785	Power Kw:	110
Bodytype:		Body colour	Stonewashed Blue metallic
Gearbox:	Automatic	Paint type	Metallic
Transmission:	Front	Type of rims (mounted)	Steel
Fueltype:	Electric	Parking lot	356
Number of seats	5		
Type of rims (mounted)	Steel		
Maintenance needed	No		

Options

Number of keys total	2	Telephone equipment
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Headlights Xenon/LED/Laser
Radio multimedia		Front parking sensors
		Rear parking sensors

Degree of wear

	215/55/18/95 T			
Winter tyres:	Fr.L.	Goodyear: 5,1 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				5.1
Tyre profile depth FR				5.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/55 R 18 95 T
Tyre size FR				215/55 R 18 95 T
Tyre size RL				215/55 R 18 95 T
Tyre size RR				215/55 R 18 95 T
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Wing RL, Chemical polution, Polish



Bumper FM, Stone chip(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Polish



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Wing FR, Scratch(es), Polish



Charging cable (normal), Missing, Replace



Bumper R, Scratch(es), Polish

