



MITSUBISHI Colt neu Colt CZ3 1.3

VIN NO XMCMNZ34A8F058997
Registration Number 4A8F058997



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20251008133251
Inspection Date / Place	2025-10-08 / Dürkop Braunschweig	Cosmetic Grade	3

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1332
Engine Size	1.3	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	142
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warranty			







Equipment

Airbag Status	Anti-lock braking	Stability control	Radio
Alloys wheels	Enhanced speaker system	Leather steering wheel	

Equipment Details


Air Conditioning	Yes	Alloy Wheel Size	14
Seat Heating	No		

Wheels & Tyres


Right Front Tyre Depth	4	Left Front Tyre Depth	4
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage


4 Schäden




1 Schäden



Component		Damage	Comments
1	Hood	Bodywork / Dent / Dent	
2	Roof	Bodywork / Dent / Dent	
3	Seat / Front Left	Interior / Ripped	
4	Bumper / Back	Paint / Scratch / Scuff	
5	Side Panel / Back Right	Bodywork / Dent / Dent	



1. Hood
Bodywork / Dent / Dent -



2. Roof
Bodywork / Dent / Dent -



3. Seat / Front Left
Interior / Ripped -



4. Bumper / Back
Paint / Scratch / Scuff -



5. Side Panel / Back Right
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

Clutch

Clutch Functioning

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)