

WIW5914E

WIW5914E · 78KWH SM Longrange · 10 September 2025 · Bochum (D)

Specifications

License Plate Number	WIW5914E	Fuel Type	Electric
Manufacturer	POLESTAR	VIN	YSMVSEGE0PL110557
Model	2	Transmission Type	Automatisch geschakelde Transmissie
Model Versions	78KWH SM Longrange	First Admission	28-10-2022
Body Type	5 door hatchback	Odometer	81.868 ^{Km}
Color	White	Numer Of Keys	1
Paint Type	Metallic	Interior	Grey
Production Year	2022	Number Headrests	5
KW	170		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Charging cable - 230v

Charging cable - 380v

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable driver's seat

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 mm	Maxxis	245 mm	45 mm	19 inch	All Season
Rear Left	6 mm	Maxxis	245 mm	45 mm	19 inch	All Season
Front Right	5 mm	Maxxis	245 mm	45 mm	19 inch	All Season
Rear Right	6 mm	Maxxis	245 mm	45 mm	19 inch	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Roof



Damage Type

Small dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part

Rear seat



Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No



Damage Part

Alloy - Left Rear



Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No



Damage Part
Reardoor - Left



Damage Type
Scratch(es)

Repair Type	Acceptable
Spray	No



Damage Part
Alloy - Left Front



Damage Type
Damaged

Repair Type	Acceptable
Acceptable	Yes



Damage Part
Hood



Damage Type
Stonechipping

Repair Type	Acceptable
Acceptable	Yes



Damage Part
Alloy – Right Front



Damage Type
Damaged

Repair Type	Acceptable
Rim repair	No



Damage Part
Alloy – Right Rear



Damage Type
Damaged

Repair Type	Acceptable
Rim repair	No



Damage Part
Bumper – Rear



Damage Type
Damaged

Repair Type	Acceptable
Spray	No