



Technician
Rutger Koogh


WIW6617E

WIW6617E · Single Motor 78kWh · 24 September 2025 · Bochum (D)

Specifications

License Plate Number	WIW6617E	Fuel Type	Electric
Manufacturer	POLESTAR	VIN	YSMVSEGE4PL166565
Model	2	Transmission Type	Automatisch geschakelde Transmissie
Model Versions	Single Motor 78kWh	First Admission	28-06-2023
Body Type	5 door hatchback	Odometer	68.019 ^{km}
Color	Black	Numer Of Keys	1
Paint Type	Metallic	Interior	Grey
Production Year	2023	Number Headrests	5
KW	170		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Charging cable - 230v

Charging cable - 380v

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable driver's seat

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Panorama roof

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance 09-07-2025

Last maintenance odometer 60.649

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Kleber	245 ^{mm}	45 ^{mm}	19 ^{inch}	All Season
Rear Left	4 ^{mm}	Fulda	245 ^{mm}	45 ^{mm}	19 ^{inch}	All Season
Front Right	4 ^{mm}	Kleber	245 ^{mm}	45 ^{mm}	19 ^{inch}	All Season
Rear Right	4 ^{mm}	Fulda	245 ^{mm}	45 ^{mm}	19 ^{inch}	All Season
Spare Tire Type	None					

Damages



Damage Part

Damage Type

Repair Type

Acceptable

Alloy - Right Rear

Damaged

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Right

Damaged

Acceptable

Yes



Damage Part

Damage Type

Notes

Repair
Type

Acceptable

Other

Dislocated / Loose

Wielkuip bescherming

Repair

No



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Front

Scratch(es)

Spray

No



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Alloys

Damaged

3 x

No

Rim repair



Damage Part

Damage Type

Repair Type

Acceptable

Tailgate

Damaged

Acceptable

Yes



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No