

## WIW5849E

WIW5849E · 78KWH SM Longrange · 10 September 2025 · Bochum (D)

### Specifications

License Plate Number	WIW5849E	Fuel Type	Electric
Manufacturer	POLESTAR	VIN	YSMVSEGE5PL110053
Model	2	Transmission Type	Automatisch geschakelde Transmissie
Model Versions	78KWH SM Longrange	First Admission	17-10-2022
Body Type	5 door hatchback	Odometer	77.714 <sup>Km</sup>
Color	White	Numer Of Keys	1
Paint Type	Metallic	Interior	Grey
Production Year	2022	Number Headrests	5
KW	170		

## Images





## Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Charging cable - 230v

Charging cable - 380v

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable driver's seat

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

## Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 mm	Maxxis	242 mm	45 mm	19 inch	All Season
Rear Left	6 mm	Michelin	242 mm	45 mm	19 inch	All Season
Front Right	5 mm	Maxxis	242 mm	45 mm	19 inch	All Season
Rear Right	6 mm	Michelin	242 mm	45 mm	19 inch	All Season
Spare Tire Type	None					

Damages



Damage Part  
Alloy - Left Rear



Damage Type  
Damaged

Repair Type  
Rim repair

Acceptable  
No



Damage Part  
Alloy - Left Front



Damage Type  
Damaged

Repair Type  
Rim repair

Acceptable  
No



Damage Part  
Hood



Damage Type  
Stonechipping

Repair Type  
Acceptable

Acceptable  
Yes



Damage Part

spoiler FB

Damage Type

small dents / small scratches

Repair Type

Plastic Repair

Acceptable

No



Damage Part

Bumper - Front

Damage Type

Damaged

Repair Type

Spotrepair

Acceptable

No



Damage Part

Alloy - Right Front

Damage Type

Damaged

Repair Type

Rim repair

Acceptable

No





Damage Part

Alloy - Right Rear

Damage Type


Stickers

Repair Type

Rim repair

Acceptable

No



Damage Part

Bumper - Rear

Damage Type

Damaged

Repair Type

Touch-up

Acceptable

No



Damage Part

Interior

Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No