

WIW5819E

WIW5819E · Long Range Single Motor 78kWh fwd · 10 September 2025 ·
Bochum (D)

Specifications

License Plate Number	WIW5819E	Fuel Type	Electric
Manufacturer	POLESTAR	VIN	YSMVSEGE5PL144669
Model	2	Transmission Type	Automatisch geschakelde Transmissie
Model Versions	Long Range Single Motor 78kWh fwd	First Admission	24-02-2023
Body Type	5 door hatchback	Odometer	67.923 ^{Km}
Color	White	Numer Of Keys	1
Paint Type	Metallic	Interior	Grey
Production Year	2023	Number Headrests	5
KW	165		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Charging cable - 230v

Charging cable - 380v

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable driver's seat

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 mm	Bridgestone	242 mm	45 mm	19 inch	All Season
Rear Left	6 mm	Michelin	242 mm	45 mm	19 inch	All Season
Front Right	5 mm	Bridgestone	242 mm	45 mm	19 inch	All Season
Rear Right	6 mm	Michelin	242 mm	45 mm	19 inch	All Season
Spare Tire Type	None					

Damages



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Reardoor – Left	Scratch(es)	Stootlijst	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Dent(s) & Scratch(es)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Headlight – Left	Scratch(es)	Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
spoiler FB	Dislocated / Loose	Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Damaged	Velgen beschadigd	Rim repair	No