


WIW6108E

WIW6108E · Long Range Single Motor 78kWh fwd · 11 September 2025 ·
Dorfmark (DE)

Specifications

License Plate Number	WIW6108E	Fuel Type	Electric
Manufacturer	POLESTAR	VIN	YSMVSEGE8PL144830
Model	2	Transmission Type	Automatisch geschakelde Transmissie
Model Versions	Long Range Single Motor 78kWh fwd	First Admission	27-02-2023
Body Type	5 door hatchback	Odometer	82.316 ^{Km}
Color	Blue	Numer Of Keys	1
Paint Type	Metallic	Interior	Grey
Production Year	2023	Number Headrests	5
KW	165		

Images





Accessories

ABS	Electric windows front
Airbags	Electrically adjustable driver\''s seat
Alloy wheels	Electrically adjustable exterior mirrors
Audio System	Fog lights
Automatic air conditioning	Front & rear parking sensors
Bluetooth car kit	Leather steering wheel
Central door locking	Navigation system
Centre armrest	Rear view camera
Charging cable - 230v	Roller cover / parcel shelf
Charging cable - 380v	Seat heating
Cruise control	Steering wheel multifunction
Electric rear windows	

Condition

Condition exterior Adequate	Last maintenance odometer 53.107
Condition interior Adequate	Previous Repairs Unknown
Last Maintenance 25-11-2024	

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 ^{mm}	Maxxis	245 ^{mm}	45 ^{mm}	19 ^{inch}	All Season
Rear Left	5 ^{mm}	Maxxis	245 ^{mm}	45 ^{mm}	19 ^{inch}	All Season
Front Right	5 ^{mm}	Maxxis	245 ^{mm}	45 ^{mm}	19 ^{inch}	All Season
Rear Right	5 ^{mm}	Maxxis	245 ^{mm}	45 ^{mm}	19 ^{inch}	All Season
Spare Tire Type	None					

Damages



Damage Part
Fender – Rear Right



Damage Type
Small dent(s)

Repair Type
Restyle

Acceptable
No



Damage Part
Alloy – Right Rear



Damage Type
Damaged

Repair Type
Rim repair

Acceptable
No



Damage Part
Alloy – Right Front



Damage Type
Damaged

Repair Type
Rim repair

Acceptable
No



Damage Part
Windscreen – Front



Damage Type
Chipped

Repair Type
Window Repair

Acceptable
No



Damage Part
Alloy – Left Front



Damage Type
Damaged

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Bumper – Rear



Damage Type
Small scratch(es)

Repair Type
Acceptable

Acceptable
Yes



Damage Part

Tailgate



Damage Type

Damaged



Repair Type

Spray

Acceptable

No