


WIW5917E

WIW5917E · 78KWH SM Longrange · 4 September 2025 · Bochum (D)

Specifications

License Plate Number	WIW5917E	Fuel Type	Electric
Manufacturer	POLESTAR	VIN	YSMVSEGE9PL110539
Model	2	Transmission Type	Automatisch geschakelde Transmissie
Model Versions	78KWH SM Longrange	First Admission	28-10-2022
Body Type	5 door hatchback	Odometer	82.886 ^{Km}
Color	Black	Numer Of Keys	1
Paint Type	Metallic	Interior	Grey
Production Year	2022	Number Headrests	5
KW	170		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Charging cable - 230v

Charging cable - 380v

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable driver's seat

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance 05-10-2024

Last maintenance odometer 57.676

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 mm	Continental	245 mm	45 mm	19 inch	All Season
Rear Left	4 mm	Michelin	245 mm	45 mm	19 inch	All Season
Front Right	4 mm	Continental	245 mm	45 mm	19 inch	All Season
Rear Right	4 mm	Michelin	245 mm	45 mm	19 inch	All Season
Spare Tire Type	None					

Damages



Damage Part	Damage Type	Repair Type	Acceptable
Rear seat	Stains & dirt	Cleaning	No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy - Right Rear	Damaged	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Right	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Right	Damaged	Acceptable	Yes

Acceptable




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Damaged	Rim repair	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper – Front	Scratch(es)	En ontzet	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Windscreen – Front	Stonechipping	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Alloy - Left Rear	Damaged	Rim repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Rear	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	small dents / small scratches	Panelbeating & Spray	No