

Inspection Protocol



POLESTAR 2 LONG RANGE DUAL MOTOR PERFORMANCE, 476HK, 2023

Vehicle information

License plate	UEG52M	Inspected by	T.H.
Year model	2023	Date of inspection	2025-04-14
Manuf. year/month	2022-07	City	Björkvik
First day in traffic	2022-09	Keys	1
Colour	MÖRKBLÅMETALLIC	Service book	Elektronisk servicebok
Mileage	32 470 km	Latest service	-
Fuel	EI (EV)	Mileage at the latest service-	
Transmission	Automat	Summer tires	Däck utan fälgar 5/5/5/5
Engine effect	350 kW	Winter tires	alu-fälg odubbat 5/5/5/5

Damages

Location	Damage	Comments	Costs excluding VAT
Bumper, Rear	Repor, 3-10 cm		100 €
Boot lid, Boot lid	Scratches 30-100 mm		100 €
Door, Rear right	Scratches above 100 mm		230 €
Glass, Windshield	Chip		30 €

Total excl. VAT	460 €
-----------------	-------

Images

[See all images in large format](#)























Stötfångare Bak Repor, 3-10 cm 1 100 kr





Bagagelucka Bagagelucka Repor 3-10 cm 1 100 kr





Dörr Höger bak Repor över 10 cm 2 500 kr





Glas Vindruta Stenskott 300 kr