

Inspection Protocol



VOLVO V70 2.4D

Vehicle information

License plate	KBM830	Inspected by	M.H.
Year model	2010	Date of inspection	2025-04-10
Manuf. year/month	2009-09	City	Sundsbruk
First day in traffic	2009-10	Keys	2
Colour	Ljusgrå	Service book	Ja
Mileage	380 760 km	Latest service	-
Fuel	Diesel	Mileage at the latest service-	
Transmission	Geartronic	Summer tires	17" alu-fälg 5/4/2/1
Engine effect	129 kW	Winter tires	17" alu-fälg 6/5/5/4

Damages

Location	Damage	Comments	Costs excluding VAT
Service	Due now		450 €
Recond	Interior		70 €
Rims & Tires, Summer	2 tires below 3 mm		270 €
Boot lid, Boot lid	Other	Trög/knarrande dörr	70 €
Bumper, Rear	Dents		300 €
Bumper, Rear	Other	Lock saknas	10 €
Boot lid, Boot lid	Other	Torkare, sitter fel/hänger	30 €
Wing, Rear right	Paint damages	Rost	180 €
Door, Rear right	Scratches above 100 mm		230 €
Door, Rear right	Scratches above 100 mm		230 €
Sills, Right	Scratches 30-100 mm		100 €
Inredning, Backseat	Damages		180 €
Inredning, Other	Damages	Mellersta handsfack, grop	180 €
Sills, Right	Other	Spricka, över 10cm	360 €
Tak, Tak	Paint damages	Rost	360 €
Wing, Front right	Paint damages	Rost	180 €
Glass, Windshield	Cracks long (Above 150 mm)		630 €
Bumper, Front	Wide scratch		300 €
Bumper, Front	Chips, several		70 €
Other, Other	Regskylt fram inbuktningar		10 €
Bumper, Front	Other	Logga saknas	20 €
Wing, Front left	Paint damages	Rost	180 €
Door, Front left	Scratches above 100 mm		230 €
Door, Front left	Paint damages	Rost	90 €
Door, Front left	Paint damages	Stenskott	70 €
Insteg, Front left	Scratches		140 €
Sills, Left	Scratches 30-100 mm		100 €

Total excl. VAT

5 040 €

[Images](#)

[See all images in large format](#)

































