



VOLVO S60

S60 D4 Geartronic

VIN NO YV1FSA8CFG2414815
Registration Number CFG2414815



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-03-01	-	2	133991 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2006-04-29	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250924111334
Inspection Date / Place	2025-09-24 / BCA Neuss	Cosmetic Grade	5

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	Grey	Engine Size (cc)	1969
Engine Size	2.0	No of Doors	4
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	113

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

USB Socket	Alloys wheels	Auxiliary Socket	Cruise control
Headlamp wash/wipe	Remote central locking	Xenon headlamps	Electrically folding wing mirrors
Radio	Airbag Status	Anti-lock braking	Bluetooth telephone interface
Diesel particulate filter	Remote adjusting wing mirrors	Satellite navigation	CD Player
Leather steering wheel	Rear parking sensors		


Equipment Details

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Seat Heating	Front		


Wheels & Tyres

Right Front Tyre Depth	8	Left Front Tyre Depth	8
Right Rear Tyre Depth	7	Left Rear Tyre Depth	7

30 Schäden



6 Schäden

6/15 - Report Number P20250924111334

13	Corner Bumper / Front Left	Paint / Scratch / Scuff
14	Rim / Front Left	Out of Bodywork / Scratch
15	Fender / Front Left	Bodywork / Dent / Dent
16	Fender / Front Left	Bodywork / Dent / Dent
17	Fender / Back Left	Bodywork / Dent / Dent
18	Door / Front Left	Paint / Scratch / Scuff
19	Door / Back Left	Paint / Scratch / Scuff
20	Roof	Bodywork / Dent / Dent
21	Roof	Bodywork / Dent / Dent
22	Roof	Bodywork / Dent / Dent
23	Bumper / Back	Bodywork / Dent / Dent
24	Corner Bumper / Back Right	Paint / Scratch / Scuff
25	Fender / Back Right	Paint / Scratch / Scuff
26	Fender / Back Right	Paint / Scratch / Scuff
27	Fender / Back Right	Paint / Scratch / Scuff
28	Tailgate	Paint / Scratch / Scuff
29	Door / Back Right	Paint / Scratch / Scuff
30	Door / Front Right	Paint / Scratch / Scuff
31	Door / Front Right	Paint / Scratch / Scuff
32	Door / Front Right	Paint / Scratch / Scuff
33	Fender / Front Right	Paint / Scratch / Scuff
34	Fender / Front Right	Paint / Scratch / Scuff
35	Fender / Front Right	Paint / Scratch / Scuff
36	Rim / Front Right	Out of Bodywork / Scratch



1. Pillar / Back Left
Bodywork / Dent / Dent -



2. Panel Filling / Back Left
Interior / Holed -



3. Panel Filling / Back Left
Interior / Scratched -



4. Panel Filling / Back Right
Interior / Holed -



5. Panel Filling / Back Right
Interior / Holed -




6. Panel Filling / Back Right
Interior / Scratched -



7. Panel Filling / Front Right Interior / Holed -



8. Windshield / Front Paint / Chipping -




9. Hood Bodywork / Dent / Dent -



10. Corner Bumper / Front Right Paint / Scratch / Scuff -



11. Corner Bumper / Front Right Paint / Scratch / Scuff -




12. Bumper / Front Paint / Scratch / Scuff -




13. Corner Bumper / Front Left
Paint / Scratch / Scuff -



14. Rim / Front Left
Out of Bodywork / Scratch -



15. Fender / Front Left
Bodywork / Dent / Dent -




16. Fender / Front Left
Bodywork / Dent / Dent -




17. Fender / Back Left
Bodywork / Dent / Dent -




18. Door / Front Left
Paint / Scratch / Scuff -




19. Door / Back Left
Paint / Scratch / Scuff -



20. Roof
Bodywork / Dent / Dent -



21. Roof
Bodywork / Dent / Dent -



22. Roof
Bodywork / Dent / Dent -




23. Bumper / Back
Bodywork / Dent / Dent -




24. Corner Bumper / Back Right
Paint / Scratch / Scuff -




25. Fender / Back Right
Paint / Scratch / Scuff -



26. Fender / Back Right
Paint / Scratch / Scuff -




27. Fender / Back Right
Paint / Scratch / Scuff -



28. Tailgate
Paint / Scratch / Scuff -



29. Door / Back Right
Paint / Scratch / Scuff -



30. Door / Front Right
Paint / Scratch / Scuff -



31. Door / Front Right
Paint / Scratch / Scuff -



32. Door / Front Right
Paint / Scratch / Scuff -



33. Fender / Front Right
Paint / Scratch / Scuff -



34. Fender / Front Right
Paint / Scratch / Scuff -



35. Fender / Front Right
Paint / Scratch / Scuff -



36. Rim / Front Right
Out of Bodywork / Scratch -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Service Light	⚠
Tire Pressure Monitoring System	✓		

Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Status / EML	⚠	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	NA	Coolant Fluid	✓
--------------	----	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		✔	
✔ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
❗ <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
☐ <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)