



VOLVO XC90

XC90 T8 AWD Recharge Geartronic

VIN NO YV1LFBMUDM1677043
Registration Number UDM1677043



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-06-01	2	2	111890 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2020-07-30	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250516091725
Inspection Date / Place	2025-05-16 / BCA Neuss	Cosmetic Grade	5

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Plug - in Hybrid Electric Vehicle Petrol	Gearbox Type	Automatic
Colour	Blue	Engine Size (cc)	1969
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	7
Seat Covering Name	Beige	Seat Covering	Leather
Charging Cables	Type 2	WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Tinted Glass	USB Socket	Airbag Status	Anti-lock braking
Cruise control	Front parking sensors	Headlamp wash/wipe	Reversing Camera
Satellite navigation	Sunroof	Electrically folding wing mirrors	Leather steering wheel
Radio	Tow ball	360°camera	Alloys wheels
Bluetooth telephone interface	Enhanced speaker system	Head up Display	Remote adjusting wing mirrors
Roof rails	Stability control	Electrically adjustable seats	Electric tailgate
LED Headlamps	Rear parking sensors		


Equipment Details

Tow Ball Type	Pivoted	Air Conditioning	Four Zone Climate Control
Alloy Wheel Size	21	Seat Heating	Front and Rear
Sunroof Type	Opening Panoramic		

Wheels & Tyres

Right Front Tyre Depth	8	Left Front Tyre Depth	8
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage



Component		Damage	Comments
1	B Pillar / Center Left	Paint / Scratch / Scuff	
2	Pillar / Back Left	Paint / Scratch / Scuff	
3	Rocker Panel / Center Right	Paint / Scratch / Scuff	
4	Pillar / Back Right	Bodywork / Dent / Dent	
5	Corner Bumper / Front Right	Paint / Scratch / Scuff	
6	Bumper / Front	Paint / Scratch / Scuff	
7	Bumper / Front	Bodywork / Dent / Dent	
8	Corner Bumper / Front Left	Paint / Scratch / Scuff	
9	Fender / Front Left	Paint / Scratch / Scuff	
10	Rim / Front Left	Out of Bodywork / Scratch	
11	Door / Front Left	Bodywork / Dent / Dent	
12	Door / Front Left	Bodywork / Dent / Dent	
13	Door / Front Left	Bodywork / Dent / Dent	

14	Door / Front Left	Bodywork / Dent / Dent
15	Door / Back Left	Bodywork / Dent / Dent
16	Door / Back Left	Paint / Scratch / Scuff
17	Door / Back Left	Paint / Scratch / Scuff
18	Side Panel / Back Left	Bodywork / Dent / Dent
19	Wing Expander / Back Left	Paint / Scratch / Scuff
20	Corner Bumper / Back Left	Paint / Scratch / Scuff
21	Tailgate	Bodywork / Dent / Dent
22	Tailgate	Bodywork / Dent / Dent
23	Tailgate	Bodywork / Dent / Dent
24	Corner Bumper / Back Right	Paint / Scratch / Scuff
25	Side Panel / Back Right	Bodywork / Dent / Dent
26	Wing Expander / Back Right	Paint / Scratch / Scuff
27	Wing Expander / Back Right	Paint / Scratch / Scuff
28	Door / Back Right	Bodywork / Dent / Dent
29	Door / Back Right	Bodywork / Dent / Dent
30	Door / Back Right	Paint / Scratch / Scuff
31	Door / Back Right	Paint / Scratch / Scuff
32	Door / Front Right	Paint / Scratch / Scuff
33	Door / Front Right	Bodywork / Dent / Dent
34	Door / Front Right	Bodywork / Dent / Dent
35	Rim / Front Right	Out of Bodywork / Scratch
36	Fender / Front Right	Paint / Scratch / Scuff




2. Pillar / Back Left
Paint / Scratch / Scuff -




3. Rocker Panel / Center Right
Paint / Scratch / Scuff -




4. Pillar / Back Right
Bodywork / Dent / Dent -




5. Corner Bumper / Front Right
Paint / Scratch / Scuff -



6. Bumper / Front
Paint / Scratch / Scuff -



7. Bumper / Front
Bodywork / Dent / Dent -




8. Corner Bumper / Front Left
Paint / Scratch / Scuff -




9. Fender / Front Left
Paint / Scratch / Scuff -




10. Rim / Front Left
Out of Bodywork / Scratch -




11. Door / Front Left
Bodywork / Dent / Dent -




12. Door / Front Left
Bodywork / Dent / Dent -




13. Door / Front Left
Bodywork / Dent / Dent -



14. Door / Front Left
Bodywork / Dent / Dent -




15. Door / Back Left
Bodywork / Dent / Dent -



16. Door / Back Left
Paint / Scratch / Scuff -



17. Door / Back Left
Paint / Scratch / Scuff -




18. Side Panel / Back Left
Bodywork / Dent / Dent -



19. Wing Expander / Back Left
Paint / Scratch / Scuff -



20. Corner Bumper / Back Left
Paint / Scratch / Scuff -




21. Tailgate
Bodywork / Dent / Dent -




22. Tailgate
Bodywork / Dent / Dent -



23. Tailgate
Bodywork / Dent / Dent -



24. Corner Bumper / Back Right
Paint / Scratch / Scuff -



25. Side Panel / Back Right
Bodywork / Dent / Dent -




26. Wing Expander / Back Right
Paint / Scratch / Scuff -



27. Wing Expander / Back Right
Paint / Scratch / Scuff -



28. Door / Back Right
Bodywork / Dent / Dent -




29. Door / Back Right
Bodywork / Dent / Dent -



30. Door / Back Right
Paint / Scratch / Scuff -



31. Door / Back Right
Paint / Scratch / Scuff -



32. Door / Front Right
Paint / Scratch / Scuff -



33. Door / Front Right
Bodywork / Dent / Dent -



34. Door / Front Right
Bodywork / Dent / Dent -



35. Rim / Front Right
Out of Bodywork / Scratch -



36. Fender / Front Right
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	AC / Heating System	✓
Parking Sensors / Cameras Functioning	✓		

Hybrid/EV

Charge Lead Condition	✓	Charge Port Condition	✓
Hybrid System Fault	✓		

Levels

Brakes Fluid	NA	Coolant Fluid	NA
--------------	----	---------------	----

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)