



VOLVO XC90: 2AHL567

Vinnnummer:	YV1LFBMVD1747764	Versionname:	2.0 T8 4WD Geartr Inscription Expr. 7PL
First Registrationdate:	6/04/2021	Fiscalpower:	
Expertise Mileage:	109273	Power Kw:	288
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2306
Fueltype:	Electric		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar collapsible
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Degree of wear

235/55/19/92 H				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				235/55 R 19 92 H
Tyre size FR				235/55 R 19 92 H
Tyre size RL				235/55 R 19 92 H
Tyre size RR				235/55 R 19 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	1		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	638,98
Bonnet, Scratch(es), Acceptable	0,00



Bumper F, Scratch(es), Repair and paint (complete)

346,88



Wing RL, Bad repair, Check

0,00



Door RL, Dent(s), Paintless dent repair

93,06



Door FL, Dent(s) and scratch(es), Acceptable

0,00



Wing FL, Scratch(es), Acceptable

0,00



Alloy rim FL polished, Scratch(es), Acceptable

0,00



Wing trim FL, Scratch(es), Acceptable

0,00



Charging cable (fast), Missing, Check

0,00



Bumper moulding R, Scratch(es), Acceptable

0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

199,04



Wing RR, Chemical polution, Polish

0,00

