



Volvo XC90 (MKL): 2AUU801

Vinnumber:	YV1LFBMVDN1776264	Versionname:	XC90 Inscription Expr. 2.0T8 Hybrid 303pk 5p 7pl AWD Geartr.
First Registrationdate:	28/07/2021	Fiscalpower:	
Expertise Mileage:	152795	Power Kw:	223
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	over 108 dagen of 1753km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	235/55/19/105 V			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				235/55 R 19 105 V
Tyre size FR				235/55 R 19 105 V
Tyre size RL				235/55 R 19 105 V
Tyre size RR				235/55 R 19 105 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	1		

Seat cover FL, Worn, Acceptable



Bumper F, Scratch(es), Repair and paint (complete)



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing trim FL, Scratch(es), Repair and paint (complete)



Alloy rim FL polished, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Bumper R, Scratch(es), Repair and paint (complete)



Bumper moulding R, Broken, Replace



Tailgate / Boot, Dent(s), Paintless dent repair



Door RR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Charging cable (normal), Missing, Check

